

intelliGen Ship Loose or Service Parts

Description of Ship loose/Service Part	Part Number	List Price
Transducer Replacement Kit	28911202	\$346.00
Temperature Sensor Kit - White Leads*	89904903	\$75.00
Pressure Transducer Harness	22515102	\$239.00
EXV Replacement Kit		
E2V11BWAE0 - 3/8" x 3/8" Conn	29326101	\$1,190.00
E2V24BWAE0 - 3/8" x 3/8" Conn	29326201	\$1,190.00
E2V24BSME0 - 5/8" X 5/8" Conn	29326401	\$1,190.00
E3V45BSME0 - 7/8" X 1 3/8" Conn	29326501	\$2,339.00
E2V11BWAE0 - 7/8" X 1 3/8" Conn	29326601	\$2,339.00
Expansion Valve molded connector - 40" Conn (Bipolar Valves)	22592101	\$216.00
Transformers		
120/24 volt - 40 VA	22529601	\$110.00
240/24 volt - 40 VA	22529602	\$111.00
460/24 - 40 VA	22529603	\$135.00
600/24 - 40 VA	22529701	\$185.00
iRC Main Control Board Replacement Kit	28918001S	\$1,214.00
iRCUI User Interface Replacement Kit	28918201S	\$821.00
iWC Webservice Card Replacement Kit	28918301S	\$1,076.00
iIC Integration Card Replacement Kit	28918401S	\$622.00
Cable Ribbon. iRC-UI to iRC Center Mount Unit Cooler 8" Replacement Kit	22602101	\$152.00
Cable Ribbon. iRC-UI to iRC - Low Profile Unit Cooler 14" Replacement Kit	22602102	\$300.00
Cable Ribbon. iRC-UI to iRC- Medium Profile and Large Unit Cooler 24" Replacement Kit	22602104	\$453.00
Cable Ribbon. iRC-UI to iRC - Large Unit Cooler 35" Replacement Kit	22602103	\$603.00
EV-COM Cable- Large Unit Cooler DUAL iRC Board Replacement Kit	22596801	\$754.00
Door Switch Kit (includes door switch and 2 ft cable)	22543102	\$279.00

*Only the sensor with white leads is shipped as a service replacement part